



Adjust correct position of hall sensors via back EMF before connecting motor to driver!

							KELLY CONTROLS, LLC		
Mark	Subarea	Signatory	Date	05/2010			Hall/Phase timing(120°)		
Design	Steven	Stand	Fany	modification	Number	Proportion	V1.0		
Assessor	Daniel								
Technics		Authorize	Steven						
Sum									